



Parts Included:






B Screen Support Bracket (2)




Hardware Pack



A Modesty Panel



B Modesty Support Bracket (2 or 3)




Hardware Pack

Part no. 1b4z6d rev C.

Tools Needed:



Power Driver



#18 Drill Bit



Phillips Bit




Tape Rule




Safety Glass


HermanMiller

Screen:






- 1. Determine where Screen is to be installed onto work surface. Note: Center of Bracket is 5 5/8" from edge of screen.
- 2. Position one Screen Bracket (B) onto Work Surface.
- 3. Using Screen Bracket as template, drill four 1/8" pilot holes 1/2" deep.



4. Remove Bracket and install onto Screen (A) using 2 Thread Cutting Screws (C). Repeat for remaining Screen Bracket (B). See Bracket locations above.




- 5. Position Screen onto Work Surface. Install 4 Tapping Screws (D) using Pilot Holes previously drilled.
- 6. Drill Pilot Holes for other Bracket using Bracket as template and ensuring that step is against edge of Work Surface.
- 7. Install 4 Tapping Screws (D).

Herman Miller

Part no. 1b4z6d rev C.

Modesty Panel:



- 8. Install Modesty Brackets (B) onto Modesty Panel (A) using 2 Thread Cutting Screws (C) per Bracket.
- 9. Place Modesty Panel onto bottom of Work Surface at desired location.
- 10. Attach Panel to Surface with 4 Tapping Screws (D) per Bracket.

HermanMiller Part no. 1b4z6d rev C.

Disassembly and Recycling:

Materials Identification and Segregation:

Where possible, plastic components are marked with ASTM recycling codes. Use these codes to identify material type for recycling. Non marked components should be treated as mixed plastic. Ferrous metals can be identified using a small magnet for recycling. Non-ferrous metals should be separated and recycled separately. To disassemble product, reverse steps 10 through 3.