




Parts Included:






Bracket Kit

Tools Required:




HermanMiller

Part no. 1b5pzg rev B.





- Lay Modesty Panel (A) face down.
 Set Side Brackets (B) and Top Brackets (C) over pilot holes on Panel.
 Secure Brackets to Panel with Tapping Screws (D).

Part no. 1b5pzg rev B. **HermanMiller**




- 4. Lay Desk on top.
- 5. Set Modesty Panel onto Desk Top.
- 6. Align Top Brackets (C) with pilot holes in Desk Top, either flush or inset.
- 7. Secure Modesty Panel to Desk Top with Screws (D).






HermanMiller

Part no. 1b5pzg rev B.



Note: Top of Modesty Panel should be aligned with top of Leg.

- 8. Using Modesty Panel Mounting Brackets (B) as template drill 1/8" pilot holes 1/2" deep into Leg. 2 Places.
- 9. Secure Modesty Panel to Leg with Screws (D).



HermanMiller

Part no. 1b5pzg rev B.

Disassembly and Recycling:

Materials Identification and Segregation:

Where possible, plastic components are marked with ASTM recycling codes. Use these codes to identify material type for recycling. Non marked components should be treated as mixed plastic. Ferrous metals can be identified using a small magnet for recycling. Non-ferrous metals should be separated and recycled separately.

To disassemble product, reverse steps 9 through 1 and also do the following: