


HermanMiller

Thrive Surface Mounted Screen (Y1116, Y1118) Installation and Disassembly for Recycling Instructions




How to assemble your Surface Mounted Screen

Tools Required



Parts Included




Assembly Instructions:

Y116 Surface Mounted Screen


Step 1

1.1 Attach LH & RH Screen Brackets and Center screen bracket to Screen with pan head screws.




1.2 If screen is to be attached to end of table where a wall attached leg is installed, switch middle bracket with end screen brackets. This will give clearance between bracket and leg.

1.3 If Cable Trough is to be installed onto screen, place screen flat on clean surface. Position brackets onto screen. Place Cable Trough over brackets. Install pan head screws.




1.3 Position screen assembly up to table at desired location with 1" gap between screen and edge of table.

1.4 Mark screw holes. Remove screen assembly. Drill pilot holes. Make sure not to drill through work surface.



1.5 Return screen to table. Secure in place with sheet metal screws.



Disassembly for Recycling:

Materials Identification and Segregation:

Where possible, plastic components are marked with ASTM recycling codes. Use these codes to identify material type for recycling. Non marked components should be treated as mixed plastic. Ferrous metals can be identified using a small magnet for recycling. Non-ferrous metals should be separated and recycled separately.

To disassemble product, reverse steps 1.5 through 1.1.

For more information about our products and services please visit us at hermanmiller.com or call (800) 851 1196.

©2017 Herman Miller, Inc., Zeeland, Michigan Printed in U.S.A. Part No. 1BKW6X – A