


Parts Included:




Tools Required:



Safety Glasses

Assembly Instructions:




- 1. Hook Lip of Coat Hook under edge of Architectural Top Cap.
- 2. Press Top Cap down onto wall assembly.

Herman Miller

Part no. 1b6x1w rev C.

Standard Coat Hook: Top Cap Ledge-Lip-Cladding



- 1. Remove Top Cap from Wall.
- 2. Holding Coat Hook at angle, place Lip on Coat Hook under Ledge on Wire Trough. Let Coat Hook rest against Cladding.
- 3. Return Top Cap to Wall.

Part no. 1b6x1w rev C.

Disassembly for Recycling:

Materials Identification and Segregation:

Where possible, plastic components are marked with ASTM recycling codes. Use these codes to identify material type for recycling. Non marked components should be treated as mixed plastic. Ferrous metals can be identified using a small magnet for recycling. Non-ferrous metals should be separated and recycled separately.

To disassemble product, reverse the above installation steps.